

Installation guide

19" rack mounting frame for MAX 505

This box contains:



1x




1x



10x



25x




10x



10x

Needed tools:



1. Place the frame in the designated area.
Note: line the frame up with the matching holes on the case. Four holes should be on the handle side of the case.



2. Carefully drill a small pilot hole in the 22 circular inserts around the lip of the case with the drill bit provided.
Note: Maximum depth pilot hole 6 mm.



3. Screw the frame to the case with the screws provided. (22x)



4. Attach the provided clamps underneath the frame according to the size of your device.



5. Fix your 19" unit with the screws and rubber rings provided.